


 <h2 style="text-align: center;">IECEX CoC Certified Service Facility</h2>	
INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification Scheme for Explosive Atmospheres <small>for rules and details of the IECEX Scheme visit www.iecex.com</small>	
Certificate No.:	IECEX SIM S0003 issue No.:2
Status:	Current Date of Issue: 2014-01-03
Applicant:	JATCO (Australia) Pty Ltd t/a Applied Resolution Technologies Lot 521 Sullivans Road Yamba NSW 2464 Australia
Type of Service:	Repair and Overhaul according to IEC 60079-19
Type of Protection:	Intrinsic Safety "i"
Scope of Service:	Repair and Overhaul of Intrinsically Safe Alignment Lasers
Locations covered by this Certificate:	JATCO (Australia) Pty Ltd Lot 521 Sullivans Road Yamba NSW 2464 Australia
Facility Audit Report:	AU/SIM/FAR10.0001/04
<small>This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEX Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEX Scheme Rules, IECEX 03 and Operational Documents as amended.</small>	
Approved for issue on behalf of the IECEX Certification Body:	David Turner
Position:	Director - Engineering, Testing and Certification Centre
Signature:	_____
Date:	_____
1. This certificate and schedule may only be reproduced in full. 2. This certificate is not transferable and remains the property of the issuing body. 3. The Status and authenticity of this certificate may be verified by visiting the Official IECEX Website .	
Certificate issued by: <div style="display: flex; justify-content: space-around; align-items: center; margin-top: 20px;"> <div style="text-align: center;"> <p>Safety in Mines Testing and Research Station (Simtars) 2 Smith Street REDBANK QLD 4301 Australia</p> </div> <div style="text-align: center;">  </div> </div>	